



ASSURANT®

Voyager Indemnity Insurance Company
PO Box 202142
Florence, SC 29502
www.assurant.com

August 10, 2022

HARI HARAN MOTE
3933 RAVENSFIELD DR
3933 RAVENSFIELD DR MI 48188

Claim Information

Insured:	Doordash Inc	Claim Number:	00103669788
Member Driver:	Tyler Scherman	Policy Number:	FAR140002100
Cause of Loss:	Property Damage-Liability	Date of Loss:	05-14-2022

This letter has been sent to: hariharanmotte@gmail.com

Dear Hari Haran Mote,

Our review of your claim has been completed. A payment in the amount of \$859.15 has been issued and mailed separately. A breakdown of your payment is below.

Repair / Replacement Amount:	\$0.00
Less Depreciation Amount:	\$0.00
Payment Amount:	\$859.15

Payment Made Payable to:	Hari Haran Mote
Payment Mailed to:	Hari Haran Mote 3933 Ravensfield Dr howell, MI 48188

If you have questions about your claim, or you have additional information that you would like us to consider, please contact us at the number below. Our office hours are 8 a.m. to 6 p.m. Monday through Friday.

Sincerely,

Colbert Guerrier
Claims Examiner
Global P&C Claims
T. 877-900-0345 Ext. 4032862
F. 866-728-7098
E. myclaiminfo@assurant.com

Enclosure: Incoming

cc: Hari Haran Mote
 Doordash Inc

Date: 8/10/2022 11:30 AM
 Estimate ID: 00103669788
 Estimate Version: 0
 Committed
 Profile ID: * Standard - MI
 Quote ID: 109971084

Days to Repair:3

Assurant, Inc.

Estimate is not an indication of coverage or liability acceptance.

Estimator: John Romano

Damage Assessed By: John Romano
 Classification: Field

ALL SUPPLEMENTS REQUIRE PRIOR APPROVAL
 To file a supplement, please visit the following WEBSITE:
 SHOPS.SNAPSHEET.ME
 For questions or assistance please call (888) 317-8527.

Type of Loss: Collision
 Date of Loss: 6/14/2022
 Deductible: 0.00
 Claim Number: 00103669788

Claimant: HARI HARAN MOTE
 Address: 3933 RAVENSFIELD DR, 3933 RAVENSFIELD DR, MI 48188
 Owner: HARI HARAN MOTE
 Address: 3933 RAVENSFIELD DR, 3933 RAVENSFIELD DR, MI 48188
 Telephone:
 Contact Phone: (734) 896-1725

Mitchell Service: 911817

Description: 2022 Chevrolet Camaro 2SS
 Body Style: 2D Cpe
 VIN: 1G1FH1R76N0104243
 Mileage: 6,733
 OEM/ALT: O
 Color: grey
 Options: PASSENGER AIRBAG, POWER DRIVER SEAT, POWER LOCK, POWER WINDOW, POWER STEERING REAR WINDOW DEFOGGER, AIR CONDITION, CRUISE CONTROL, TILT STEERING COLUMN AM/FM STEREO, DRIVER AIRBAG, HEATED EXTERIOR MIRROR, REAR (DUAL-ZONE) AC LEATHER SEAT, POWER PASSENGER SEAT, FRONT SIDE AIRBAG WITH HEAD PROTECTION PREMIUM SOUND SYSTEM, ANTI-LOCK BRAKE SYS., TRACTION CONTROL, ALUM/ALLOY WHEELS REARVIEW CAMERA, TIRE INFLATION/PRESSURE MONITOR, MEMORY SEAT, ANTI-THEFT SYSTEM AUXILIARY INPUT, BLUETOOTH WIRELESS CONNECTIVITY, LEATHER STEERING WHEEL SATELLITE RADIO, POWER ADJUSTABLE EXTERIOR MIRROR, AUTO AIR CONDITION FIRST ROW BUCKET SEAT, TELEMATIC SYSTEMS, SIDE AIRBAGS SECOND ROW SIDE AIRBAG WITH HEAD PROTECTION, REMOTE DECKLID OR TAILGATE RELEASE MP3 PLAYER, HEATED STEERING WHEEL, DAYTIME RUNNING LIGHTS ELECTRONIC PARKING AID, ELECTRONIC STABILITY CONTROL, EXTERIOR MEMORY MIRRORS FRONT COOLED SEATS, FRONT HEATED SEATS, HEAD UP DISPLAY, KEYLESS ENTRY SYSTEM LIMITED SLIP DIFFERENTIAL, REAR SPOILER, SIDE BLIND ZONE ALERT, SMART KEY SYSTEM

Drive Train: 6.2L Inj 8 Cyl 10A RWD
 License: DZE9345 MI
 Search Code: None

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/Part Number	Dollar Amount	Labor Units
<u>Side Body</u>							
1	101780	BDY	REPAIR	R Section Quarter Panel			2.0* #
2		REF	REFINISH	R Quarter Panel Outside			C 2.4
3	100054	BDY	REMOVE/INSTALL	R Rocker Cover			0.5
<u>Quarter Glass</u>							

ESTIMATE RECALL NUMBER: 08/10/2022 11:30:07 00103669788
 Mitchell Data Version: OEM: JUN_22_V

Software Version: 7.1.242

Copyright (C) 1994 - 2022 Mitchell International
 All Rights Reserved

Date: 8/10/2022 11:30 AM
 Estimate ID: 00103669788
 Estimate Version: 0
 Committed
 Profile ID: * Standard - MI
 Quote ID: 109971084

4	101229	GLS	REPAIR	R Qtr Glass Stationary mask	Existing			0.5* #
5								
				<u>Rear Lamps</u>				
6	101181	BDY	REMOVE/INSTALL	R Rear Combination Lamp				0.3 #
7		BDY	REMOVE/INSTALL	R Rear Body Side Trim Panel				0.3 #
8	101442	BDY	REMOVE/REPLACE	R Rear Side Marker Lamp Assembly	23126884	26.22		INC #
				<u>Rear Bumper</u>				
9	101481	BDY	REMOVE/INSTALL	Rear Bumper Cover				1.4 #
10	103249	BDY	REPAIR	Rear Bumper Cover	Existing			1.5* #
11		REF	REFINISH	Rear Bumper Cover				C 2.4 #
				<u>Special/Manual Entry</u>				
12	900500	REF *	REFINISH/REPAIR	basecoat reduction - full clear	Existing			-0.5*
				<u>Additional Operations</u>				
13		REF	ADD'L OPR	Clear Coat				1.4
				<u>Special/Manual Entry</u>				
14	900500	BDY *	REMOVE/REPLACE	Flex Additive	New		8.00 *	0.0*
				<u>Additional Operations</u>				
15	933005	BDY	ADD'L OPR	Restore Corrosion Protection			10.00 *	0.2*
16	933018	BDY *	ADD'L OPR	Mask For Overspray			5.00 *	0.2*
				<u>Additional Costs & Materials</u>				
17			ADD'L COST	Paint/Materials			176.70 *	
18			ADD'L COST	Hazardous Waste Disposal			3.00 *	

* - Judgment Item
 # - Labor Note Applies
 C - Included in Clear Coat Calc

Estimate Totals

I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary	Amount
Body	6.4	49.00	15.00	0.00	328.60	Taxable Parts	34.22
Refinish	5.7	49.00	0.00	0.00	279.30	Sales Tax @ 6.000%	2.05
Glass	0.5	49.00	0.00	0.00	24.50		
Non-Taxable Labor					632.40	Total Replacement Parts Amount	36.27
Labor Summary	12.6				632.40		
III. Additional Costs					Amount	IV. Adjustments	Amount
Taxable Costs					179.70	Insurance Deductible	0.00
Sales Tax @ 6.000%					10.78	Customer Responsibility	0.00
Total Additional Costs					190.48		
Paint Material Method: Rates Init Rate = 31.00 , Init Max Hours = 99.9, Addl Rate = 31.00							
						I. Total Labor:	632.40
						II. Total Replacement Parts:	36.27
						III. Total Additional Costs:	190.48
						Gross Total:	859.15
						IV. Total Adjustments:	0.00
						Net Total:	859.15

Date: 8/10/2022 11:30 AM
Estimate ID: 00103669788
Estimate Version: 0
Committed
Profile ID: * Standard - MI
Quote ID: 109971084

Point(s) of Impact

4 Right Rear Side (P)

Insurance Co: Assurant, Inc.

Inspection Site: HARI HARAN MOTE
Address: 3933 RAVENSFIELD DR
3933 RAVENSFIELD DR, MI 48188

Body Shop: N/A

Any person who knowingly presents a false or fraudulent insurance claim for the payment of a loss may be guilty of a crime and may be subject to fines and confinement in state prison.

This estimate has been prepared based on the use of aftermarket crash parts supplied by a source other than the manufacturer of your motor vehicle. The aftermarket crash parts used in the preparation of this estimate are warrantied by the manufacturer or distributor of such parts, rather than the manufacturer of your motor vehicle.

SNAPSHEET ESTIMATE SUMMARY
DAMAGE CONSISTENT WITH FOL?:

Yes

ESTIMATE REVIEW

R&I and repair scraped rear bumper cover on RT side. Repair scraped/dented RT qtr panel

ALT PART EXPLANATION

NA - repair only

POTENTIAL HIDDEN DAMAGE

none

UNRELATED PRIOR DAMAGE

none seen





























